

Quick release claw - Blanking plug



Description

Blanking plug

Max operating pressure

10 bar

Temperature

-5°C to +60°C

Construction

Brass body


Description

Reference

EXP BRE

Description

Blanking plug



Dimensions

Reference	A mm	B mm
EXP BRE	57	30